




Wear gloves when handling lead



Don't eat or drink when working with lead



Don't smoke when working with lead



Apply a barrier cream before starting work



Keep your hands away from your face



Don't bite your fingernails and keep them cut short



**LEAD SHEET ASSOCIATION**

**LEADWORKER'S SAFETY**



Scrub hands thoroughly when you finish work and before eating or smoking



If possible, use a proper hand cleaner



Use heavy duty hand wipes if running water is not available



Wear a mask when welding



Wear a mask when stripping old lead



Make sure masks are clean. Check filters or use disposable masks



Use tissues rather than a handkerchief




Beards can prevent masks sealing properly



Remove work wear before leaving site



Handle dusty overalls with care



Wash overalls separately



Ensure your blood lead levels are tested regularly